



Figure B-6. Animal intrusion at CFA-01 Landfill I (PD020605-22).




Figure B-7. Institutional control sign at CFA-02 Landfill II. (PD020605-04).



Figure B-8. View of CFA-02 Landfill II looking northwest, with sparse vegetation in foreground and moisture monitoring network in the background (PD020605-05).





Figure B-9. Erosion rill at CFA-02 Landfill II, northwest portion of landfill (PD020605-07).



Figure B-10. Detail of erosion rill in northwest corner of CFA-02 Landfill II showing depth of rill (PD020605-10).





Figure B-11. Rock armor at CFA-02 Landfill II (PD020605-11).